## **LITE FENCE GUARD WARRANTY**

Lite Fence Guard has a 1-year limited warranty, against cracking, peeling and fading. Aer-Flo Sports sole responsibility shall be for the replacement of product only, when it has been determined by Aer-Flo Sports that the product was defective as a result of manufacturing and not as a result of improper installation or handling.

Aer-Flo Sports assumes no liability or responsibility for any direct, indirect or consequential damages that may arise from the use of any product manufactured by Aer-Flo Sports.

As to the testing of our Fence Guard profile we received a rating not to exceed Delta E of 8 Hunter units due to manufacturing defect within 1 year.

## STANDARD FENCE GUARD WARRANTY

Standard Fence Guard has a 3-year limited warranty, against cracking, peeling and fading. Aer-Flo Sports sole responsibility shall be for the replacement of product only, when it has been determined by Aer-Flo Sports that the product was defective as a result of manufacturing and not as a result of improper installation or handling.

Aer-Flo Sports assumes no liability or responsibility for any direct, indirect or consequential damages that may arise from the use of any product manufactured by Aer-Flo Sports.

As to the testing of our Fence Guard profile we received a rating not to exceed Delta E of 8 Hunter units due to manufacturing defect within 3 years.

## PREMIUM FENCE GUARD WARRANTY

Premium Fence Guard has a 5-year limited warranty, against cracking, peeling and fading. Aer-Flo Sports sole responsibility shall be for the replacement of product only, when it has been determined by Aer-Flo Sports that the product was defective as a result of manufacturing and not as a result of improper installation or handling.

Aer-Flo Sports assumes no liability or responsibility for any direct, indirect or consequential damages that may arise from the use of any product manufactured by Aer-Flo Sports.

As to the testing of our Fence Guard profile we received a rating not to exceed Delta E of 8 Hunter units due to manufacturing defect within 5 years.